



CONSTRUCTION UPDATES & ACTIVITIES
Week Ending of January 27, 2017

San Luis Obispo Instructional Building

Work this week: The metal framing contractor continued their placement of the second floor exterior infill. The cantilever deck shoring has been completely removed. The second floor beams were prime painted, and the first floor beams have begun to be sprayed with the fireproofing. The roof-top mechanical pads have been formed by the concrete contractor.

- Noise:** Some noise
- Parking:** Some permanent parking loss
- Utilities:** None
- Odors:** None
- Dust:** Moderate dust impact
- Vibrations:** Minor vibrations
- Vision:** None

