

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending October 27, 2023

5300 Tile Roof Repair

Work this week: The contractor mobilized this week to begin the tile roof repair at Building 5300. Removal of the existing tile and underlayment has been completed and new underlayment and rolled roofing has been installed. The wire tie system is in place.

Noise: Power tools & lifting equipment.

Parking: No personal vehicles on site.

Utilities: No impact Odors: None



Roof Substrate



Underlayment/Rolled Roofing



Wire Tie System





