

Measure L Bond Program SLOCCCD CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES


Week Ending of December 9th, 2016

San Luis Obispo Instructional Building

Work this week: The mansard decking is currently approximately 90% complete. The electrical contractor pulled wire for the main feed from the point of connection to the transformer. The plumbing contractor is nearly finished with the installation of the waste line on the second floor. The decking and edge form for the shoring systems is also complete.

Noise:	Loud equipment noise due to steel erection
Parking:	Some parking loss for the duration of the project
Utilities:	None
Odors: Dust:	Some welding odors Moderate dust impact
Vibrations: Vision:	Minor vibrations Bright arc flashes









TOGETHER, BUILDING VALUE EVERY DAY.

