



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending March 17, 2017

San Luis Obispo Instructional Building

Work this week: The interior stairwell walls were framed. The roofing contractor has continued their installation of the single ply roofing, the exterior sheathing has begun to be installed, and the Mechanical, Electrical, & Plumbing contractors have continued to rough in their work on the first and second floors. Necessary stabilization work of the site was preformed due to the recent storms.

Noise:	Some noise
Parking:	Some permanent parking loss
Utilities:	None
Odors:	None
Dust:	Moderate dust impact
Vibrations:	Minor vibrations
Vision:	None

