



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending April 07, 2017

North County Campus Center

Work this week: The framing/plaster contractor continues interior and exterior framing on the first and second floors, and continues scaffold installation around the perimeter of the building. The plumber is installing roof drain piping, the HVAC contractor has begun to install ductwork on the second floor. The electrician continues laying out and installing conduit and boxes throughout the building and the fire protection contractor continues installing fire sprinkler piping at the second floor. The concrete contractor started installing roof-top concrete curbs and placed the footings for the exterior stairs.

Access:	No access into Fenced Const. Zone
Noise:	Moderate noise from equipment and framing operations
Parking:	Parking Lot 10-minor loss of spaces
Utilities:	None
Odors:	None
Dust:	Minimal

