



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending May 5, 2017

San Luis Obispo Instructional Building

Work this week: The exterior columns have been framed and sheathing of these columns has begun. The sunshade angles are continuing to be installed. Framing of the partition walls on the second floor is continuing, and the MEP (mechanical, electrical, & plumbing) contractors are continuing with the rough-in of their systems.

- Noise:** Some noise
- Parking:** Some permanent parking loss
- Utilities:** None
- Odors:** None
- Dust:** Moderate dust impact
- Vibrations:** Minor vibrations
- Vision:** None

