



## CONSTRUCTION UPDATES & ACTIVITIES

*Week Ending May 19, 2017*

### San Luis Obispo Instructional Building

**Work this week:** The elevator arrived and the installation has begun. The contractor is placing insulation on the first floor, while priority walls continue to be dry-walled. A crane was on site to lift the boiler equipment, additional equipment pads, and assist in repositioning the rails for one of the air conditioning units on the roof.

<b>Noise:</b>	Some noise
<b>Parking:</b>	Some permanent parking loss
<b>Utilities:</b>	None
<b>Odors:</b>	None
<b>Dust:</b>	Moderate dust impact
<b>Vibrations:</b>	Minor vibrations
<b>Vision:</b>	None

