



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending June 2, 2017

San Luis Obispo Instructional Building

Work this week: The metal framing is complete on the first floor, and the first and second layer of drywall has been set in multiple classrooms. The window installation continues on the second floor exterior windows. Throughout the building, MEP (mechanical, electrical, and plumbing) rough-in advances, as well as the elevator installation. Moving to the exterior of the building, the air barrier installation is underway as well.

Noise:	Some noise
Parking:	Some permanent parking loss
Utilities:	None
Odors:	None
Dust:	Moderate dust impact
Vibrations:	Minor vibrations
Vision:	None

