



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending June 2, 2017

North County Campus Center

Work this week: The roofing contractor began the install of single ply roofing underlayment at the flat roofs, while the framing contractor progresses with the installation of drywall on the first and second floors. The framing contractor is also working to complete the exterior framing and sheathing at the stair locations. The plumbing, electrical, heating ventilation and air-conditioning, and framing work remains ongoing alongside the sheet metal and flashing at the openings.

- Access:** No access into fenced const. zone & modified pedestrian access route around the site on Dallons Drive
- Noise:** Moderate noise from equipment and framing operations
- Parking:** Minor loss of parking in Parking Lot 10
- Utilities:** None
- Odors:** None
- Dust:** Minimal

