



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending June 9, 2017

North County Campus Center

Work this week: The framing contractor is continuing to install drywall and insulation 1st and 2nd floors. The roofing contractor has started to install the single ply roofing underlayment, tapered insulation, and the single ply membrane on the main roof. The plumbing, electrical, HVAC, and framing rough-in work continues. The sheet metal and flashing at the openings are ongoing, and the glazing contractor has begun to install the window frames.

- Access:** No access into fenced const. zone
Modified pedestrian access around site work on Dallons Drive
- Noise:** Moderate noise from equipment and framing operations
- Parking:** Parking Lot 10-minor loss of spaces
- Utilities:** None
- Odors:** None
- Dust:** Minimal

