

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week of July 10th, 2017

San Luis Obispo Instructional Building

Work this week: Taping of the second floor walls continues as walls have been insulated and drywall placed. The mechanical contractor is installing ducting on the roof, while the plumber is installing supports for their piping. Metal lath and paper has continued to be installed on the exterior of the building. The electrical contractor is working on their rough in to connect to the mechanical units.

Noise: Some noise

Parking: Some permanent parking loss

Utilities: None Odors: None

Dust: Moderate dust impact **Vibrations:** Minor vibrations

Vision: None









