

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending July 21, 2017

San Luis Obispo Instructional Building

Work this week: The electrician is working on the conduit at the first floor cable trays, as well as bringing conduit to the light fixtures in the soffits on the second floor. Taping is continuing on the second floor. The plumbers have been on the roof working on connecting the pumps, boiler and air separators. Metal lath and paper has continued to be installed on the exterior of the building.

Noise: Some noise

Parking: Some permanent parking loss

Utilities: None Odors: None

Dust: Moderate dust impact **Vibrations:** Minor vibrations

Vision: None









