



CONSTRUCTION UPDATES & ACTIVITIES
Week Ending October 20, 2017

San Luis Obispo Instructional Building

Work this week: The concrete contractor poured the walkway on the west side of the building. Painting has continued on the second floor mainly focusing on the interior doors. The plumbing contractor has been installing his finishes within the bathrooms on the second floor. The electrician has installed the fixtures in the stairwell. Classroom furniture was delivered to the first floor.

- Noise:** Some noise
- Parking:** Some permanent parking loss
- Utilities:** None
- Odors:** None
- Dust:** Moderate dust impact
- Vibrations:** Minor vibrations
- Vision:** None

