



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending October 20, 2017

North County Campus Center

Work this week: The project’s contractors continue to install piping and controls’ wiring for the HVAC equipment on the rooftop. The interior HVAC ductwork, electrical (conduit and pulling of wire), interior and exterior painting, communications, data, fire protection piping, and controls are also ongoing. The installation of the curtain wall system is moving forward. The trellis-shade roof was installed and is being painted, and the site-finish grading, road base, site electrical, and site concrete are ongoing.

- Access:** No access into fenced const. zone
- Noise:** Moderate noise from equipment
- Parking:** Parking Lot 10-minor loss of spaces
- Utilities:** None
- Odors:** None
- Dust:** Dust control being performed

