



CONSTRUCTION UPDATES & ACTIVITIES
Week Ending November 17, 2017

North County Campus Center

Work this week: The curtain wall glazing in the main entry to the building is being installed. Mechanical, electrical, plumbing, fire protection, acoustical ceilings, painting, drywall finishing, kitchen equipment and elevator installation continues. The contractor began installation of the interior doors, and tile is being set in the 2nd floor restrooms. Medium Voltage cable was pulled to the building. Data, communication, and audio visual cable is being pulled, and the installation of landscape irrigation continues.

- Access:** No access into Fenced Const. Zone
- Noise:** Moderate noise from equipment
- Parking:** Parking Lot 10-minor loss of spaces
- Utilities:** None
- Odors:** None
- Dust:** Dust control being performed

