

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending February 16, 2018

North County Campus Center

Work this week: The high-ceiling panel installation was completed this week. The exterior concrete was placed and finished throughout the week on the west side of the building. The flooring contractor started placing carpet tile in the second floor offices. The painters sprayed their finish coat on the exterior stairs. Site grading is continuing on the north and northeast side of the building

Access: No access into fenced construction zone
Noise: Moderate noise from equipment

Parking: Parking Lot 10-minor loss of spaces

Utilities: None Odors: None

Dust: Dust control being performed









