

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending of February 24th, 2017

San Luis Obispo Instructional Building

Work this week: The fire sprinkler rough-in is 90% complete on the first floor. The mechanical, electrical, and plumbing contractors continue their work on the first floor as well. The exterior sheathing at the mansard roof is almost complete, and the roof hatch has been installed. Walls on the first floor have continued to be framed, and the glazing contractor has attached their angles for the exterior shade fins.

Noise: Some noise

Parking: Some permanent parking loss

Utilities: None None

Dust: Moderate dust impact

Vibrations: Minor vibrations

Vision: None









