

**CONSTRUCTION UPDATES & ACTIVITIES**
*Week Ending April 21, 2017***San Luis Obispo Instructional Building**

Work this week: The window framing contractor has begun to install window and door frames. The drywall contractor has started the installation of the exterior sheathing on the second floor. Painting of the exterior mansard eaves has begun, and the MEP contractors have continued to rough in their systems on the first and second floors.

Noise:	Some noise
Parking:	Some permanent parking loss
Utilities:	None
Odors:	None
Dust:	Moderate dust impact
Vibrations:	Minor vibrations
Vision:	None

