



CONSTRUCTION UPDATES & ACTIVITIES
Week Ending April 28, 2017

San Luis Obispo Instructional Building

Work this week: The building's fire line was installed and has passed inspection. The HVAC contractor is continuing to install duct on the second floor. Windows and window frames continue to be installed on the first floor. The window contractor is also installing flashing around the windows on the second floor. Metal framing continues throughout the building.

- Noise:** Some noise
- Parking:** Some permanent parking loss
- Utilities:** None
- Odors:** None
- Dust:** Moderate dust impact
- Vibrations:** Minor vibrations
- Vision:** None

