



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending May 26, 2017

San Luis Obispo Instructional Building

Work this week: The elevator install continues to progress. The first floor dry wall and second floor metal framework work maintains forward momentum. While heating, ventilation, and air-conditioning ductwork is being installed in the second floor corridor and the plumbing rough in begins within the second floor walls.

Noise:	Some noise
Parking:	Some permanent parking loss
Utilities:	None
Odors:	None
Dust:	Moderate dust impact
Vibrations:	Minor vibrations
Vision:	None

