



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending June 30, 2017

North County Campus Center

Work this week: The roofer has begun installing insulation and plywood on the high roof. Plumbing, electrical, and HVAC rough-in work continues. Insulation and drywall are being installed on the first and second floors, and the window sill sheet metal and flashing install are ongoing. The glazing contractor continues the installation of windows, and the parking lot expansion is progressing.

- Access:** No access into fenced const. zone
Modified Pedestrian Access around site work on Dallons Drive
- Noise:** Moderate noise from equipment and framing operations
- Parking:** Parking Lot 10-minor loss of spaces
- Utilities:** None
- Odors:** None

