

**CONSTRUCTION UPDATES & ACTIVITIES***Week Ending July 28, 2017***San Luis Obispo Instructional Building**

Work this week: The plaster has begun to be installed on the exterior of the building. The roofers began to lay out and attach the clay tiles to the roof. Seismic bracing of mechanical, plumbing and electrical components above ceiling are continuing and the electrician continued pulling wire on the second floor. The plumbing contractor has continued installation of the boiler and air separator on the roof.

Noise:	Some noise
Parking:	Some permanent parking loss
Utilities:	None
Odors:	None
Dust:	Moderate dust impact
Vibrations:	Minor vibrations
Vision:	None

