



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending October 13, 2017

San Luis Obispo Instructional Building

Work this week: The electrician is near completion of the A/V finish in the first-floor classrooms and is trenching for the site lighting power connections. The plumbing contractor has installed the gas pressure regulator and earthquake valve on the exterior of the building. The ceiling grid continues in the second-floor offices, and the concrete sidewalks have continued to be formed and placed around the building.

- Noise:** Some noise
- Parking:** Some permanent parking loss
- Utilities:** None
- Odors:** None
- Dust:** Moderate dust impact
- Vibrations:** Minor vibrations
- Vision:** None

