

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending November 17, 2017

San Luis Obispo Instructional Building

Work this week: The light fixtures in the meeting rooms have been installed and powered. A portion of the concrete benches in the plaza area have been poured, and the site has been graded around them. The HVAC registers have been installed and connected to ducting in the metal ceiling grid, and the first-floor classrooms have been completed, and a punch-list walk occurred with the Architect.

Noise: Some noise

Parking: Some permanent parking loss

Utilities: None None

Dust: Moderate dust impact **Vibrations:** Minor vibrations

Vision: None









