

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending December 8, 2017

North County Campus Center

Work this week: The installation of the high ceiling continues, the skylight installation is near completion, and the curtain wall system is moving forward. The 2nd floor restroom tile is complete allowing the plumbers and electricians to be released in those areas, and the 1st floor restroom tile us underway. Electricians are pulling and terminating wire in preparation for the startup of the permanent power to the building

Access: No access into fenced construction zone

Noise: Moderate noise from equipment

Parking: Parking Lot 10-minor loss of spaces

Utilities: None Odors: None

Dust: Dust control being performed









