



CONSTRUCTION UPDATES & ACTIVITIES
Week Ending March 16, 2018

North County Campus Center

Work this week: The casework has been delivered into the building and has begun to be installed in their respective rooms. The tile contractor has placed his tile in the interior stair treads; while the painter painted all components in the cafeteria ceiling. Work continues in the kitchen, lockers have been installed and the flooring contractor has continued to place carpet in the first floor.

- Access: No access into fenced construction zone
- Noise: Moderate noise from equipment
- Parking: Parking Lot 10-minor loss of spaces
- Utilities: None
- Odors: None
- Dust: Dust control being performed

