



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending April 6, 2018

North County Campus Center

Work this week: The feature wall has been installed and painted in the bookstore. The floor and wall tile has begun to be installed in the kitchen and cafeteria serving area. The traffic coating was installed on the roof terrace area. The concrete contractor has poured the last of the site concrete, and the electrician has continued working on installing the lighting and cables in the cafeteria area. The fire alarm system has begun to be tested.

- Access:** No access into fenced construction zone
- Noise:** Moderate noise from equipment
- Parking:** Parking Lot 10-minor loss of spaces
- Utilities:** None
- Odors:** None
- Dust:** Dust control being performed

