

Measure L Bond Program SLOCCCD CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending April 27, 2018


North County Campus Center

Work this week: The limestone floor tile continues to be installed in the first floor lobby. Furniture has been installed throughout the building and the computer workstations are being installed. The vinyl flooring installation in the cafeteria began and is about 95% complete. The kitchen and serving area equipment is also being installed. The planters around the building were filled with soil and are ready for the landscape contractor to install irrigation and plants.

Access:	No access into fenced construction zone
Noise:	Moderate noise from equipment
Parking:	Parking Lot 10-minor loss of spaces
Utilities:	None
Odors:	None
Dust:	Dust control being performed









TOGETHER, BUILDING VALUE EVERY DAY.

