

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending May 4, 2018

North County Campus Center

Work this week: The contractors have begun to remove their trailers and storage containers. The electrician installed the exterior site light poles. Limestone floor tile has been grouted and caulked in the first floor lobby area. Quartz countertops are being installed at the drinking fountains and in the workrooms. The Audio/Visual contractor is installing the TV monitors and connecting the lecterns and presentation systems. The kitchen equipment contractor is continuing their installation in the serving and kitchen area.

Access: No access into fenced construction zone
Noise: Moderate noise from equipment
Parking: Parking Lot 10-minor loss of spaces

Utilities: None Odors: None

Dust: Dust control being performed









