



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending May 11, 2018

North County Campus Center

Work this week: The landscape contractor has installed the river rock underneath the exterior stairs. Countertops in the workrooms and at the drinking fountains have been installed, and the sinks and drinking fountains are being installed. The standing desk and second floor reception desk countertops began installation and the vinyl flooring in the cafeteria has been completed.

- Access:** No access into fenced construction zone
- Noise:** Moderate noise from equipment
- Parking:** Parking Lot 10-minor loss of spaces
- Utilities:** None
- Odors:** None
- Dust:** Dust control being performed

