



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending September 15, 2023

SLO Campus Center

Work this week: This week, the contractor started forming building perimeter walls on the west 1/3 of the building. Electrical contractor continued installation of under slab electrical conduit. Elevator Pit drain line & backfill was completed.


Site utility contractor continued installation of site storm drain utility, and backfilling of site electrical trench from the POC into the building.

- Noise:** Loud noise from equipment & trucking
- Parking:** No Impacts
- Utilities:** No Impacts
- Odors:** None



Bldg. Perimeter Wall Forms

Under Slab Electrical Conduit



Under Slab Electrical Conduit



Site Storm Drain



Site Electrical into Bldg.