



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending October 13, 2023

SLO Campus Center

Work this week: The contractor poured concrete slab on grade in the east 1/3 of the building. Under slab base material is being installed on the west 1/2 of the building slab.

Site utility contractor was not onsite this week.

- Noise:** Loud noise from equipment & trucking
- Parking:** No Impacts
- Utilities:** No Impacts
- Odors:** None



Perimeter Wall Curb (East Side)



Slab On Grade (East Side)



Slab On Grade (East Side)



Underslab Base (West Side)



West Perimeter Ftg. Concrete