



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending October 20, 2023

SLO Campus Center

Work this week: The contractor continued pouring concrete slab on grade in the east 1/3 of the building. Perimeter wall form boards and under slab plumbing are being installed on the west 1/3 of the building.

Site utility contractor was not onsite this week.

- Noise:** Loud noise from equipment & trucking
- Parking:** No Impacts
- Utilities:** No Impacts
- Odors:** None



Perimter Wall Curb (East Side)

Slab On Grade (East Side)



Under Slab Plumbing (West)



Under Slab Plumbing (West)



West Perimeter Form Boards