

Measure L Bond Program SLOCCCD

CONSTRUCTION UPDATE



CONSTRUCTION UPDATES & ACTIVITIES

Week Ending November 3, 2023

SLO Campus Center

Work this week: The contractor continues forming perimeter footing and wall form boards on the west 1/3 of the building. Under slab vapor barrier & slab on grade rebar was installed on the west 1/3 of the building. Slab concrete was place on a portion of the west 1/3 of the building.

Site utility contractor was not onsite this week.

Noise: Loud noise from equipment &

Parking: No Impacts
Utilities: No Impacts
Odors: None





Under Slab Vapor Barrier & Rebar (West Side)



Electrical Rm. Wall Curb Forms



Restroom Slab & Curb (West Side)



Slab Pour (West Side)





